



**Steps 1-3**. Attach extrusions to canopy using 2 **long** knobs per extrusion. Attach canopy haves using black plastic latches. Attach standoffs. Insert 1 **long** knob as shown in lower left.



Step 4. Insert plex w/ pre-installed puck lights. Attach one 3-way power splitter to left 3 lights and one to right 3 lights.



Steps 5&6. Attach left and right lower columns to feet using 2 short thumb knobs per column. Install gusset caps.






Steps 7&8. Attach left and right lower columns to upper columns using 2 short thumb knobs.



Step 9. Slide 2-piece graphic bars together.





**Step 11**. Slide canopy supports onto columns and tighten **short** knobs.





Step 12. Place canopy onto canopy supports.



Step 13. Attach V-legs to counter using 1 long knob per leg..



Rev2

Step 14. Attach V-leg counter to backwall & bases using 3 long knobs.



Step 15. Attach header using standoff caps & wings using wing grippers.



## exhibitline

