

<u>exhibitline</u>

Steps 1-3. Attach extrusions to canopy using 2 **long** knobs per extrusion. Attach canopy haves using black plastic latches. Attach standoffs. Insert 1 **long** knob as shown in lower left.



Step 4. Insert plex w/ pre-installed puck lights. Attach one 3-way power splitter to left 3 lights and one to right 3 lights.




Steps 5&6. Attach left and right lower columns to feet using 2 short thumb knobs per column. Install gusset caps.



Steps 7&8. Attach left and right lower columns to upper columns using 2 **short** thumb knobs.



Step 9. Slide 2-piece graphic bars together.






Step 11. Slide canopy supports onto columns and tighten short knobs.



Step 12. Place canopy onto canopy supports.



Step 13. Attach V-legs to counters using 1 long knob per leg..





Step 14. Attach V-leg counters to backwall & bases using 3 long knobs per counter.

Step 15. Attach header using standoff caps & wings using wing grippers.



