HPC-18

Hybrid Pro™ Modular Counter 18 is a stylish counter solution for any exhibit. Available in four different finishs including grey, black, white, and natural. Designed with only 3 pieces for easy assembly.




We are continually improving and modifying our product range and reserve the right to vary the specifi cations without prior notice. All dimensions and weights quoted are approximate and we accept no responsibility for variance. E&OE. See Graphic Templates for graphic bleed specifications


features and benefits:

- Modern illuminated counter
- Wood top, available in 4 color options
- Laminate overlays the extrusion frame and matches counter top color
- Light box slides make graphics glow
- Three piece assembly for quick set up
- Packs into OCH2 portable case


dimensions:	
Hardware	Graphics
Assembled unit: 29.53"w x 39.37"h x 23.23"d 750(w) x 1000mm(h) x 590(d) Approximate Weight: 63 lbs / 29 kg	Refer to related graphic templates for more information Visit: https://www.theexhibitorshandbook.com/downloads/download-graphic-templates or click here
Shipping	additional information:
Packing case(s): 1 OCH2 Shipping dimensions: OCH2: (52 "L x 29 "H x 15 "D) 1448mm(l) x 1449mm(h) x 838mm(d) Approximate shipping weight: 98lbs / 45 kg	Graphic material: Dye-sublimation SEG push-fit fabric Panel Colors: Dove Black Designer Fusion White Maple
This product may include the following materials for recycle: aluminum, select wood, fabric, cardboard, paper, steel, and plastics.	1 person assembly recommended:


Included In Your Kit















Next connection the jumper cable that is attached to the underside of the counter top to the two LED light leads from each legs LED light.



How to Apply & Remove Graphics


Installation and removal of SEG graphics is easy!


Installation: Push the SEG bead into each corner of the frame (1-4) with your thumb, then push the SEG bead into the middle of the run (5-8) and work your way around the perimeter of the frame until all beading is pushed in properly; if necessary, go around the perimeter again to ensure beading is secure in the extrusion profile.



Note: Keep the set up area clean by using a drop cloth, washing hands before set-up or by wearing gloves.

Removal: Use the pull tab located on the graphic and gently pull the graphic from the frame, going around the perimeter.





Graphics Storage & Care

Graphics should be folded with the graphic facing inward and stored in a zip lock /sealable plastic bag. Spot clean by wiping with a damp white cloth. If washing is necessary, use a commercial size front-loading washing machine, gentle cycle with cool water. Line dry flat. Dry cleaning is NOT recommended to prevent shrinkage.